



Hall Ranch II Access Road Repair and Hazard Mitigation Weekly Construction updates

Date: 06/06/2018

By: Prashant KC

Location: South St. Vrain, West of Lyons, CO

Work in Progress/Completed

1. Completed final Inspection on May 30th
2. Official project completion date would be June 1st , 2018
3. Incorporation of As-built data into post construction model to verify proposed conditions.
4. Completed Aggregate base course road re-surfacing between St 1+25 to 22+75.
5. Completed field density testing of finished road surface.
6. Completed seeding and hydromulch in designated areas.
7. Poured new concrete Low water crossing.
8. Restored all access roads and staging areas.



Looking upstream: Seed and Hydromulch above soil riprap in road embankment slope and floodplain.



Looking upstream: new aggregate base course road at washout reach.



Hall Ranch II Access Road Repair and Hazard Mitigation Weekly Construction updates

Date: 06/06/2018

By: Prashant KC

Location: South St. Vrain, West of Lyons, CO



Looking downstream: Low water crossing ditch and outfall



Looking downstream: Concrete Low water crossing



Re-surfaced Aggregate base course road