

A scenic landscape photograph of a rocky stream. The stream flows through a meadow with dry, yellowish-brown grasses and scattered trees. In the background, a prominent red rock cliff rises under a clear blue sky. The text is overlaid on the center of the image.

South St. Vrain Creek Restoration Hall Meadows

*St. Vrain Creek Coalition Meeting
11/16/16*



Project Status

- 30% Design is complete
- Moving into Phase II



SOUTH ST VRAIN CREEK RESTORATION AT HALL RANCH

FIGURE 1: SITE MAP



List of tasks

- Prepare final design
- Generate specifications
- Prepare and obtain permits
- Update the design report
- Develop operations and maintenance plan
- Develop construction quality assurance plan
- Finalize construction costs estimates
- Address reviewer comments

Schedule

- Draft Final design—December 15, 2016
- Final design—January 31, 2017
- Permitting—now through June 2017
- Advertise project for bid—April 2017
- Select contractor—May 2017
- Construction
 - Start: post-spring run-off (late June/July)
 - End: no later than Dec 31, 2017
- Maintenance and monitoring—3 years post-construction







